

MEMORANDUM

RECEIVED

APR 13 1998

April 7, 1998

TO: Allen Merritt

FROM: Cindy Hodges *cyh*

Department
Southern Region

RE: Rock Creek Water District Measuring Device Inventory

On Thursday, April 2, 1998, I met with Chuck Helman, Watermaster of Rock Creek Water District 47-0, to inspect all measuring devices and diversion works for compliance with Department standards.

My overall impression with this Water District was that routine yearly maintenance is not being performed on the many of the devices to keep them in proper operating condition for each season, and several have simply fallen into disrepair. There have been some recent upgrades to some devices and/or diversion works which should help with regulation this season. Other upgrades or maintenance still needs to be scheduled. Mr. Helman advised me there was a resolution passed by the District this year that all IDWR recommended modifications be in place by the start of the 1999 irrigation season. Many of my recommendations include maintenance or cleaning that should be required to be done *before flows are allowed to be diverted this year*. I don't think it unreasonable that any new construction or major modifications be delayed until the end of this season.

Only about half of the gravity diversion facilities have been constructed with controllable *and* lockable works (ie, screw gate type), although most others use an adjustable slide gate which could be converted to lockable. Pump diversions are more diverse but most have a lockable gate valve. I didn't get the feeling that routine security is really an issue. On the contrary, Mr. Helman indicated that most users are cooperative and compliant and the need for physical control depends on the water user. In general I agree that the lockup policy should be only as strict as the situation demands. As a matter of equity, however, all diversions must be able to be locked if necessary.

Mr. Helman was especially concerned that a secured diversion stay secured. He had some locks and chains cut and removed last year after the diversion was posted with the orange WARNING tag. He was frustrated that IDWR did not or could not penalize this infraction. Since this act is a misdemeanor provided for outside the water law statutes, I advised that the county Sheriff be contacted on the next occurrence and a citation requested.

The other problem the Watermaster relayed to me was the difficulty of obtaining an accurate measurement over some devices at high flows. There were a few devices in place which were either not sized properly to accommodate the full recorded right, or which were set in such a manner that the device submerged at only moderate flows. An approach I have recommended is to notify owners of marginal or substandard devices that, until devices are modified or repaired, delivery will be limited only to that amount which can be accurately measured (which might be zero). If the owner wishes to receive a full allotment of water, the recommended modification will have to be completed.

Following is a list of my findings and recommendations for each site which you may share with each water user as we had discussed. Photos are also attached for your reference. If you have questions regarding any particular diversion please call me.

ROCK CREEK WATER DISTRICT DIVERSION INVENTORY

April 2, 1998

This list begins at the uppermost diversion and moves downstream, and represents no particular order of priority.

1. Helman East Side diversion.

Has not been used in some years (flows diverted at other points); ditch is overgrown. An adequate lockable diversion works and measuring device must be installed before diversion may occur.

2a. Helman North diversion, Fifth Fork

Diversion works is slide gate only with no lockable capability. Suggested that an eye bolt be fastened near the top of the slide frame and holes drilled in the gate so that it may be padlocked at various positions.

2 foot Cipolletti weir, handmade, acceptable construction. Location of weir is poor, just below a bend in the ditch. This weir should be moved downstream in the ditch at least 20 feet, possibly below the culvert, and an adequate weir pool constructed.

2b. Helman South diversion, Fifth Fork

Diversion works description and recommendation same as for North diversion. 2 foot Cipolletti weir, handmade, acceptable construction and location. The hillside above the ditch has sloughed into the weir pool and this needs to be redug when the ditch is cleaned.

3. Frazier pump and Ranchettes

Frazier pumps directly from Rock Creek. Pump is used as a booster for a deep well when not pumping from the creek. A valve may be used to regulate priority cuts. The Watermaster should verify that the intake line is removed from the creek and connected to the well after priority cutoff.

This pump has a flow meter which is reported to work OK, but which has never been calibrated by IDWR. The meter should be verified using a standard flow meter.

12 subdivided 5-acre lots, each with 3 inches of water rights, are owned by 9 individuals who also each pump directly from the creek using 3-5 HP pumps. These systems have been estimated by the Watermaster as providing approximately one-half miner's inch to each sprinkler head being operated. Each five-acre parcel is allowed no more than six sprinklers per irrigation set. There are likely no physical controls. We could require valves to be installed on discharge lines. When the Frazier meter is calibrated, it would also be a good idea to measure a few of these small systems to confirm the discharge rates. When priority cuts are made for these rights, the pumps and/or intake lines should be removed by the owners and the Watermaster should verify in some manner that each system is dismantled for the season.

4. Crockett weir

Diversion works is a sliding gate which could be made lockable by drilling a hole near the top of the slide frame and several holes in the same side of the gate so it could be secured in various positions.

Weir is not acceptable in its present condition and location. The weir blade is bent in one spot and the device is not level. It is presently placed just downstream from a sharp bend in the ditch. The device must be removed, the blade straightened, and the weir reset upstream approximately 6 feet to obtain an adequate straight run of ditch above the weir. A weir pool needs to be excavated and the weir may need to be elevated slightly in order to meet all installation criteria. If a Parshall flume is installed, the same location would be acceptable and the entry pool shouldn't be necessary.

5a. Crockett south pump

Diversion works is a 20HP pump into pressurized mainlines. There is no measuring device; Watermaster has been estimating diversion based on number of

sprinklers or lines operating. This method can be fairly accurate as long as the system is operated in a consistent manner. To be sure, this pump should be measured at all operating conditions to verify discharge. There is a valve present for adjustments and control. At priority cutoff, the pump and/or intake line should be removed and Watermaster should verify that the system is dismantled for the season.

5b. Crockett north pump

Diversion system description and recommendations same as for south pump.

6. Norton Ditch weir

Diversion works is a metal gate covering a culvert. Either a good sliding gate or screw gate must be installed. A sliding gate should be converted to a lockable works prior to installation by drilling positioning holes for a padlock.

Handmade 3' Cipolletti weir is an acceptable construction. However, weir is leaning and rubbish must be cleaned from the upstream side. After resetting device, be sure and check weir pool criteria and measuring stake for level.

7. East Ditch

Good diversion works - screw gate.

Metal 4' Parshall flume is in good condition. Should check for level at the beginning of each season.

8. Rock Creek Ranch

Good diversion works - screw gate.

Good 4' Cipolletti weir in cement structure; has developed leaks around and below the blade which must be repaired before the season for accurate measurement of all flows. There is a good spot for a permanent staff gauge on the cement sidewall approximately 4 feet upstream from the weir - not mandatory but would be a nice addition for ease of measurement. If attached, check with Watermaster for exact location and be sure bottom of gauge is level with weir crest.

9. West Ditch

Screw gates at main diversion works and also at adjusting spillway just above the weir - both OK.

6' Cipolletti weir in permanent concrete footing. Weir blade has been removed for ditch cleaning but was on site and is in good shape. Most of ditch has been cleaned but work remains in weir pool area - 1-2 feet of silt has been left against the upstream side of the weir base which must be removed for proper contraction of flows. The bank around the footing on the west side needs to be filled in and stabilized where there has been a small wash.

10. Gray pump and holding pond

Earthen pond and dam with 60HP pump. Pond level is static when pump is not operating (self regulates). A Parshall flume at this site has been removed because it was ineffective.

An old Master flowmeter installed on the pump discharge does not work consistently; these meters are not reliable for use with surface water. Watermaster has been estimating flows based on number of sprinklers or lines operating. Both electric panel and main valve on pump could be locked, providing adequate Watermaster control if required. A measurement of this pump at all operating conditions should be made with a standard meter to verify its pumping capacity. Recommend that because of potential for variable diversions at this site, gate valve might be marked or settings noted at several flow rates.

11. Gray diversion at Diana's weir

Good lockable screw gate in cement footing.

3' Cipolletti weir looks OK but needs cleaned and weir pool re-established. A new culvert downstream should take care of the exit flow problems of last year. If weir still submerges at normal to high flows, it will need to be raised and sized up to 4' crest.

12. Dulin High-line canal weir

No controllable or lockable diversion structure. Watermaster reports this diversion is seldom used and washes out easily. Only a portion of the original concrete dam is still in place. A suitable headgate is required if water user wishes to divert flows. I suggested an adjustable check gate positioned a little further down the ditch to help protect it from spring flows. The earth and rock retaining dam could be left in place on the channel until high flows subside.

3' Cipolletti weir is positioned in a permanent box just upstream from canal crossing - in good shape but weir pool needs cleaned and enlarged.

13. Funk weir at Dulin driveway

Lockable screw headgate OK.

Weir is buried in gravel - not acceptable for measurement. If ditch and downstream culvert are dug out and weir is reset, the existing 3' weir blade could likely be used. Weir crest needs to be at least 8" above bottom of ditch to provide adequate fall at anticipated high flows. There is also not quite enough distance between the outlet pipe and the weir, as the pipe emerges right into the weir pool. Elevating the weir may submerge the pipe. This could be workable but I can't say without inspecting it in operation. Positioning the weir across the road is not possible due to divergence of ditches.

14. Funk cellar pump

15HP pump with Master meter. Both electrical panel and system main valve are lockable if necessary for Watermaster control.

Meter does not always work but was verified last summer by IDWR staff and was accurate within an acceptable range at the time. System pumps to open discharge and has only one basic operating condition. It is acceptable for Watermaster to continue using last year's verified flow whenever the system is running, if that is acceptable to water user.

15. Mulberry weir on Stricker Ditch

Diversion works has good screw gate; diverting a small flow on date of inspection.

4' weir, adequate at lower flows. However, operating close to submergence at time of visit, approximately 4 cfs. At much higher flows, would not yield an accurate reading. Last year's temporary solution of an additional plate on the weir opening to raise the crest is not satisfactory for the long term. The entire weir blade needs to be raised so that the crest is at least 30" above the bottom of the ditch, to allow for sufficient operating conditions at the maximum water right flow. At this higher elevation, wing walls may have to be extended and the weir pool enlarged. Alternatively, a 5' or 6' weir could be installed; bulkhead dimensions would have to be increased accordingly.

16. Mulberry pump

60HP pump from flow-through holding pond. Pump has no flow meter, delivers to pressurized mainline. This system, like others, could have a flow meter installed, or have discharges estimated. It must be assessed with a standard meter to confirm flows at various operating conditions. All irrigated acres must be confirmed with Watermaster.

4-2 98 W/ watermaster Chuck Heeman

(Well is too small for total allowable draw)

① Mulberry - Wing walk too short, weir pool not quite adequate, well OK at lower flows but not at higher. At W.M. request to raise crest & add a gate to well to raise crest but end up w/ non-sld length hard to calculate. Has cut low last year.

Lockable gate OK (Stricker Dilah)
raise blade, dig out pool, extend wing walls
photo 1, 2, 3
to be reviewed

60 HP (W. pump)

② Mulberry pump from building ground. Apparent to be a high capacity system from ex. ditch to flat field. Best to do a system assessment. Needs head meter.

plumbing OK for 11 ft
no lockalls 1" level shut, OK?
photo 1, 2, 3
degrade

5 HP (Master)

③ Funk pump - Flowmeter doesn't work. Burke measured a few years ago @ 52 cfs, with a early D. Lockable pool OK. System fairly constant - spec discharge. Maybe to account for 30% extra. Lock - lower capacity of pump. New flywheel, installed about 2 years ago. Flowing but needs flow - valid flow? Or failure issue?

photo 1, 2, 3

(4) ^(Drain) Funk well - Not used - well buried,
 structure above ground,
 Slope plate could be used - 3" slightly bowed
 valve at least 8" from tank based on 2 c/s
 fuel flow - consistent with data
 headgate lockable etc
 photo 5

(5) Drain - Cavalier 11 - Dipped in
 Blue - 100% - seldom used - No to
 allowed below work in water pool
 otherwise suitable - jumbo
 photo 6, 7
 No control or lock etc. structure - something
 photo 8 - 9 - 10 - 11 - 12

(6) Emergency diversion (Drain) used by
 lockable gate in channel below, used
 with 3" pipe - red slope.
 Work pool needs cleaned out.
 (see photos) down to
 exit (see photos of last year)

↑
 2 diversion
 same pipe
 3" pipe
 ↓

Emergency pump 60HP
 fire water, controlled
 photo 13, 14, 15, 16, 17, 18
 unit consistent - has estimated flow using
 discharge from sprinkler. Has first priority
 out - 19 - 20

③ West bank to App weir (out for maint)

Bydack - sets pair of structure

Work pool needs atleast 2' - 1-2'
down below blade, about that much on
sides. West bank needs filled in
around footing

Photo 1

Photo 2 - looking down near weir (dam)
Photo 3 - headgate 1/2 mile up
Photo 4 - looking up

① Rock or Ponds - good 4' app blade
looking below weir, has to be polished

Good place for steel gate on
wall (not mandatory) photo 1
Photo 2 - looking up
Photo 3 - looking above weir
all fine - so it's probably a good idea
at least. (Senior review) 10/14. SS in
press - a post US

② East Ditch - all control work

area of control work
Photo 1 - looking up
Photo 2 - looking up
Photo 3 - looking up
Photo 4 - looking up
Photo 5 - looking up
Photo 6 - looking up
Photo 7 - looking up
Photo 8 - looking up
Photo 9 - looking up
Photo 10 - looking up
Photo 11 - looking up
Photo 12 - looking up
Photo 13 - looking up
Photo 14 - looking up
Photo 15 - looking up
Photo 16 - looking up
Photo 17 - looking up
Photo 18 - looking up
Photo 19 - looking up
Photo 20 - looking up
Photo 21 - looking up
Photo 22 - looking up
Photo 23 - looking up
Photo 24 - looking up
Photo 25 - looking up
Photo 26 - looking up
Photo 27 - looking up
Photo 28 - looking up
Photo 29 - looking up
Photo 30 - looking up
Photo 31 - looking up
Photo 32 - looking up
Photo 33 - looking up
Photo 34 - looking up
Photo 35 - looking up
Photo 36 - looking up
Photo 37 - looking up
Photo 38 - looking up
Photo 39 - looking up
Photo 40 - looking up
Photo 41 - looking up
Photo 42 - looking up
Photo 43 - looking up
Photo 44 - looking up
Photo 45 - looking up
Photo 46 - looking up
Photo 47 - looking up
Photo 48 - looking up
Photo 49 - looking up
Photo 50 - looking up
Photo 51 - looking up
Photo 52 - looking up
Photo 53 - looking up
Photo 54 - looking up
Photo 55 - looking up
Photo 56 - looking up
Photo 57 - looking up
Photo 58 - looking up
Photo 59 - looking up
Photo 60 - looking up
Photo 61 - looking up
Photo 62 - looking up
Photo 63 - looking up
Photo 64 - looking up
Photo 65 - looking up
Photo 66 - looking up
Photo 67 - looking up
Photo 68 - looking up
Photo 69 - looking up
Photo 70 - looking up
Photo 71 - looking up
Photo 72 - looking up
Photo 73 - looking up
Photo 74 - looking up
Photo 75 - looking up
Photo 76 - looking up
Photo 77 - looking up
Photo 78 - looking up
Photo 79 - looking up
Photo 80 - looking up
Photo 81 - looking up
Photo 82 - looking up
Photo 83 - looking up
Photo 84 - looking up
Photo 85 - looking up
Photo 86 - looking up
Photo 87 - looking up
Photo 88 - looking up
Photo 89 - looking up
Photo 90 - looking up
Photo 91 - looking up
Photo 92 - looking up
Photo 93 - looking up
Photo 94 - looking up
Photo 95 - looking up
Photo 96 - looking up
Photo 97 - looking up
Photo 98 - looking up
Photo 99 - looking up
Photo 100 - looking up

could use bridge across creek

photo 11, 12

- (11) Northern Creek weir (D. Craddock work)
3' high / handle. Sliding gate
needs to be raised. Needs to be vertical. Sliding
slightly bowed but may straighten out.
D. Craddock at [unclear] photo 11
Sliding handle adjustable, not
lockable. Don't recall work.

- (12) Craddock No. 1 pump 30 HP (rate
estimated by sprinkler discharge)
Control panel not lockable. Single valve
on outlet. photo 13
No measurement. P/D by [unclear]

- (13) Craddock South pump 20 HP - Same as above
photo 14. No device. One valve control.

- (14) Craddock weir - Not acceptable. Needs to
be relocated in straight run of ditch and
raised, well pool created. If Parshall flume
is used (1") - ditch will need to be leveled
straight photo 15, 16

DIV WORKS = Sliding gate, could be made
lockable by drilling holes in plate & one
in frame. (culvert to catch ditch water)

