

A25-02092 Summary 11/11/03

General Comments Please see comments regarding all Lombard claims in A25-00229.

This claim appears to reflect actual practice and to be consistent w/ license.

Ownership Appears to be correct

POD Three springs for stockwater and one for irrigation. I just now noticed stockwater is not claimed. See map in A25-00229 for spring locations.

One spring is at Waypoint 16, 710,867E 229,256 N
IDTM

One spring is at Waypoint 17, 710,846E 228,878N

The third spring is between these two but the GPS reading failed.

The irrigation POD is Waypoint 18,
710,724E, 228,490 N.

POU See map in A29-00229. Appears to be about 75 acres.

PROFIT

SCANNED
JUN 29 2004

Water Resources
Field Services
208 663 4667

Ernie Lombard field notes 10/22/03

- 1) Pod overlap on decres appears OK
- 2) Ernie's mother can give letter, also Bob Collins, Reed Humphreys
- 3) Reed Humphreys statement about sharing water confirmed by Ernie - apparently equal priority

A25-02092 ① Spring GPS ~~708,587E~~ ~~229,002N~~
Waypoint 015 1 photo

② Spring GPS 710,867E 229,256N
Waypoint 016 1 photo

③ Spring GPS 710,846E 228,578N
Waypoint 017 1 photo

④ Irr POD GPS ~~710,833E~~
710,724E, 228,490N
Waypoint 018

2 photos showing Pod
looking SW } W

Herman Creek } Willow Creek water
meet out from photo $\approx$ 200 yards.

Pod for pipeline
for trench

BAD #'s

SCANNED

JUN 29 2004

Water Resources
Field Services
208 663 4667

PROFILED

A25-02092 Summary 11/11/03 p2

Overlap Bottom end may overlap A25-00229.
See comments in A25-00229 Summary.

Conflict None noted unless USFWS has
competing claims.

Priority Per license

Quantity Per license

Water Use The claim suits the observed
stockwater use, you may want
to invite an amendment. The
house is supplied from a
different spring, claimant believes
he already has a partial decree
for domestic

List of Photos

A25-02092-1.jpg Middle Spring POO. Spring
is under wooden cover at the
back of the photo.

A25-02092-2.jpg Upper POO (stock pond)

PROFILED

SCANNED

JUN 29 2004

Water Resources
Field Services
208 663 4667

A25-02092 Summary 11/11/03 p3

A25-02092-3.jpg Lower spring POD. It is hard to see but inside the tire a pipeline picks up water here.

A25-02092-4.jpg POD looking SW from where creek goes under road. This is also the irrigation POD, just past the stock tank the ditches split, and right at the fence a ditch goes to the NW. Looking SW.

A25-02092-5.jpg POD from same location as #4, looking W.

Bryce A. Contor

SCANNED

JUN 29 2004

Water Resources
Field Services
208 663 4667

PROFILED