



IDAHO DEPARTMENT OF WATER RESOURCES

SNAKE RIVER BASIN ADJUDICATION - BASIN 23-27



RIGHT ID 25 13085

POD ID 174977

Folder No. A2513085

Claim Status No Longer In Use

IDTMEAST

IDTMNORTH

GPSID

Diversion Description

WELL PUMP MAINLINE 36 UNIT APT.COMPLEX,D/1,1 RV HOOKUP,STOCKWATER. was unable to contact claimant. Phone has been disconnected, and a tenant at the apartment complex said that John Sr. had moved away to live with his son. Could not locate POD or any sign of a well.

Assumptions

POD no longer in use.

Invoice #

2000-055-23-27-0

Phase-0 (No Attention)
Phase-I (Ready to Go to Field)
Phase-II (Site Visit - Data Missing)
Phase-IV (Total Complete)

Linked

Photos

GPS Accuracy (ft)

Date (M/D/Y)

Time

Flow Rate (CFS)

0.00

Open Channel Flow

☐ Complete one box from both Area and Calculation sections

Cross Sectional Area

☐ Circular Channel

- ☐ Less than half full
- ☐ Half full
- ☐ More than half full
- ☐ Full

Diameter 0

Depth 0

☐ Rectangular Channel

Width 0

Depth 0

Flow Calculation

☐ Continuity Velocity 0

☐ Orifice

(Use only for head over a pipe flowing full with free discharge)

Depth of Water above orifice centerline 0

☐ Weir

(Use only for water flowing freely over weir)

Height of water above nappe 0

Width of weir 0

☐ Manning (If used, include photo of representative channel section)

Channel Slope

Channel Description

Concrete lined	.016
Smooth earth	.025
Earth	.033
Rough bed, weeds on sides	.04
Smooth natural stream	.033
Rough natural stream	.1

Pumped System

HP 0

Pressure Head (psi)

Elevation Head (ft)

Motor Mfg

Motor Serial #

Pump Type


Pump Mfg

Pump Serial#

New Contact Information

New Contact Comments

This Form and the associated query are the exclusive intellectual property of Intrepid Technology Resources Inc. , and may not be copied, modified, or distributed without the express written consent of Intrepid Technology and Resopurces, Inc.



FOLDER NO. A2513085

7/29/02

John or Joe Burrup could not be contacted. Their number is disconnected and a tenant at the apartments said that John Sr. had moved away to live with his son. I walked around the apartments but could not locate a well.