

erb Bessey -

527-7155 7144

Emergency Management
rps of Engineers
Walla Walla, Washington

mile 845

Cor tried to maintain water rights
and did not designate whether or
not land could be farmed - just
wildings. had temp easement and
ground IPD load D.3-1 to maintain easements

Need Higher quantity
of water due to soil type

Soil is Rocky and sandy
along the Riverbank

Ditches are concrete to
combat water loss

Asked for additional EOP
on 9/23/04 and a
change of ownership

See Spatial Dynamics Map
for POD's - Could include
accomplished change in POD

Source

of acres

priority

should this be 2 days?

Source = groundwater
(according to Ernie)

of acres = 81

Missed appointment
on 9/16/04 at 9:00am
rescheduled to 9/23/04 - 9:00am

538-6835
250N 4570E
R.3 by ID
83442

PROFILED

SCANNED

JAN 12 2005

Ditch under Dyke for flood is
No longer there.

#2 Sprinkler went over top
#1 goes through culvert in levee

11/9/04 Jensen Res.

GPS Track of lawn & house
for Believed ground water use.

Army Cor. Rip-Rap on NE
corner of property

960 SW Corner was leveled

on East & POD - North of
here was always flood irrigated

to 1966 East POD was
main after that The North
as main Point.

After 1961 that's when Dan
ft to work for you't