


29-00274E

POD

Field Exam: 8/13/02



Looking East at bridge over creek. Water is diverted just North of the bridge (csaxton).



Looking North at Pump used to divert water to claimed POU. Mink Creek to the Right of the picture. Black ABS line is the intake line (csaxton)

29-00274E

POU

Field Exam: 8/13/02



Looking East at claimed POU. Creek at the base of the hill in the background of the picture (csaxton).