

29-00276D

POD

Field Exam: 9/17/02



Looking at point where pump is placed when in place. Mink Creek to left of picture. POU behind me in picture. Ditch seen in the middle of picture (csaxton).



Looking East at POD. Claimed POU behind me in picture (csaxton).


29-00276D

Ditch

Field Exam: 9/17/02



Looking West at drainage ditch coming from above the property. Could be historical ditch (csaxton).



Looking south at historical ditch that could have irrigated the claimed POU (csaxton).

29-00276D

POU

Field Exam: 9/17/02



Looking West at claimed POU. Irrigation occurs around lawn according to claimant (csaxton).