

WR: 29-00285H, 302, 306

FE: 3/4/03



Looking NE at a culver that runs under Rapid Creek road. I am standing on Mr. Morrison's property and George Chandlers property can be seen in the background. Mr. Morrison says he taps into George Chandlers system and runs a line through the culvert. No system was in place at time of the field exam. This culver is used to convey water from the gulch at the north of Mr. Morrison's property to Rapid Creek.

WR: 29-00285H, 302, 306

FE: 3/4/03



Looking West at the gulch where Mr. Morrison gets his spring water to irrigate his ground to the Left of the picture. Standing on George Chandlers property.

WR: 29-00285H, 302, 306

FE: 3/4/03



Looking East at George Chandlers property. Mr. Morrison says that this black pipe seen in the picture is used to run through the culvert to convey water to his property.