


Historical Ditch

Taken 10/3/01



Historical Point of diversion that diverted water to the ditch that carried water to the north side of the North Fork of Pocatello Creek.

Historical Ditch

Taken 10/3/01



Looking East. Signs of the old historical Ditch that carried water to the north side of Pocatello creek to flood irrigate down to as far as Angelo Trayis' place.

Historical Ditch

Taken 10/3/01



Looking West



Looking East

29-00443I

POD

Field Exam 10/02/01



Looking West. Pocatello creek to the Left of the picture (csaxton 10/25/01).

Pump information:

Centurion – Self Priming

Part: 186016-02

HP: 2

Volts: 230

Amps: SF 11.5

(csaxton 10/25/01).

29-00443I

POD

Field Exam 10/02/01



Looking North into Pocatello Creek (csaxton 10/25/01).

Pump information:

Centurion – Self Priming

Part: 186016-02

HP: 2

Volts: 230

Amps: SF 11.5

(csaxton 10/25/01).

29-00443I

POU

Field Exam 10/02/01



Looking South. Picture shows a small area that is normally irrigated when there is water in the creek (csaxton 10/25/01).

29-00443I

POU

Field Exam 10/02/01



Looking North. Claimants home in back ground. Lawn area around claimants home is irrigated from domestic well. Field is the main portion of POU irrigated from Pocatello Creek (csaxton 10/25/01).