

9-28-01: No Visible Irrigation In 1987

: Called and Phone Was to different Owners ?

: Drive to address

10-2-01: Centurion - Self Priming
FE

Part 186016-02 2 Hp pump
Volts 230 Amps 11.5

: Some Irrigation on South Side of Creek
Pump put in place over 20 yrs ago

: Looks Good Recommend without Home or lawn

: Pump in place Prior to 1987