


29-00448H

Ditch

Field Exam 5/6/03




Looking NW at where the claimant states the historic path of the conveyance ditch ran (csaxton).

29-00448H

Ditch

Field Exam 5/6/03



Looking SE at the path of an historic ditch that runs across the claimed POU (csaxton).

29-00448H

Ditch

Field Exam 5/6/03



Looking at a un-kept ditch that runs along the south side of the claimants property (csaxton).

29-00448H

Ditch

Field Exam 5/6/03



Looking East. This picture shows a pipe that would divert water between Casper and West property to feed into a ditch that is located about where I am standing when I took this picture. (csaxton).

29-00448H

POU

Field Exam 5/6/03



Looking south at claimed POU. Claimed POU is on both sides of the driveway running through the middle of the picture (csaxton).