

29-00494L

Ditches

Field Exam 8/7/01



Looking South. Terrell Creek flows South along the West side of the claimants property. I15 behind me in picture. Place of use to the Left of the Picture. (csaxton 8/8/01).

29-00494L

Ditches

Field Exam 8/7/01




Looking East. Picture shows ditch that runs on the north side of the claimants property. POU in background. (csaxton 8/8/01).

29-00494L

Ditches

Field Exam 8/7/01




Looking NE. Picture shows ditch that connects claimant ditch on North side of property and historical ditch on West side of claimant property. (csaxton 8/8/01).

29-00494L

Ditches

Field Exam 8/7/01



Picture shows where Terrell creek enters claimants property from the West and can be diverted either East or South (csaxton 8/8/01).