

29-00604A

POD

Field Exam: 8/27/02



Looking NW at POD for all Indian Creek rights with a POU south of W Portneuf RD. (csaxton).



Pump that diverts water from the ditch system. Not an actual POD since it is diverting from a ditch (csaxton).

29-00604A

POND Field Exam: 8/27/02



Looking South at pond. Indian Ck flows underneath the W. Portneuf RD into a headgate that can be used to divert water East, West, or into the pond (csaxton).



Looking North at pond. Claimed POU contains orchard and the top of the trees can be seen in this picture just above the bank of the pond (csaxton).

29-00604A

POND Field Exam: 8/27/02



Looking NW at pond (csaxton).



Looking NE at pond (csaxton).

29-00604A

POU

Field Exam: 8/27/02



Looking at flood irrigation system to the West of the claimants home. This water runs in a northerly direction along the west side of the property.



Looking North at Orchard that is part of the claimed POU (csaxton)

29-00604A

POD

Field Exam: 8/27/02



Looking North at claimed POU. Claimants home in background.



Looking at a headgate in the ditch to divert water to claimed POU (csaxton)

29-00604A

System Field Exam: 8/27/02



Looking North at headgate in main ditch used to split the water into two directions. The top of the picture shows the split that diverts water to the west side of the claimed POU (csaxton)