

29-00606A

POD

Field Exam: 8/27/02



Current POD hooked into sprinkler system. This POD and sprinkler system installed 3 or 4 yrs ago when Leo Dean inherited the property from his mother. Previous method of irrigation was flood irrigation from upstream. Must recommend historical POD (csaxton).

29-00606A

POD

Field Exam: 8/27/02



Looking South at flood irrigation POD (csaxton).



Looking at flood irrigation POD (csaxton).

29-00606A

POU

Field Exam: 8/27/02



Looking North at claimed POU. Note irrigation line in Picture (csaxton).



Looking E at claimed POU. Mink Creek shown in the picture (csaxton).

29-00606A

POU

Field Exam: 8/27/02



Looking East at claimed POU. Home to the right of picture. Non-irr field to the left (csaxton)



Looking North at claimed POU. No signs of recent irrigation (csaxton).