

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES
Staff Analysis Sheet For
SRBA Claim Verification Field Report

A51-00113
A51-02061

A. Prior to Conducting the Exam, the File Contains

- ☒ Claim Verification Report(CVR)
- ☒ ~~Copy~~ ^{Profile} of Adjudication Claim
- ☒ Copies of pertinent files(prev. rts., exams, etc.)
- ☒ N/A Well Inspection Form (If Needed)
- ☒ Copy of U.S.G.S. Quad map, orthophotoquad, or NAPP photography
- ☒ Check P.D. & P.U. desc. for Govt. Lots(if a lot is found, a copy of the Govt. plat is needed to add the lot onto the R claim file later.)
- ☒ Check CVR for P.D. overlap(see page titled Pt. of Div. Review Sheet)
- ☒ Check AJ & WR P/D indexes(to ck. accuracy of CVR overlap ckd. above)
Overlap ___yes ☒no If yes: ___copy of claims & water rights incl?
Type of Overlap? ___ Add acres or uses to existing system
___ Increase rate of flow or volume
___ Other: _____
- ☒ Check CVR for P.U. overlaps(see page titled Pl. of Use Review Sheet)
- ☒ Check AJ & WR P/U indexes(to ck. accuracy of CVR overlap ckd. above)
Overlap ___yes ☒no If yes: ___copy of claims & water rights incl?
Type of Overlap? ___ Increase rate of flow or volume
___ Add P/D's
___ Increase number of acres within tracts
___ Different source for same acres
___ Other: _____
- ☒ NO Appointment Letter Sent? *Appt. made in-office*(initial & date)
- ☒ NO Appointment Made and Telephone Conversation Memo Attached

B. After Conducting the Exam, the File Contains:

- ___ Fully Completed and Signed CVR Form
- ___ Completed Adjudication Claim Checklist
- ___ Photographs of Point(s) of Diversion and Place of Use
- ___ Completed map outlining Point(s) of Diversion and Place of Use

pw 7/12/93

①



PHOTOGRAPHER: Linda Werner
~~KAY WALKER~~

DATE OF PHOTOS 7-19-1993

FILE NO(S). A51-00113, A51-02061



POD #1
Located in
SWSW, S23,
T11S, R9E

Ditch
from above
POD to
Place of
use.



③



PHOTOGRAPHER: Linda Werner
~~RAY WALKER~~

DATE OF PHOTOS 7-19-93

FILE NO(S). A51-00113, A51-02061



POD #2
photo taken
standing by
creek looking
upstream.

Place of
use -

Pictures
taken from
north to
northeast -
see pg. 4
also



(2)



PHOTOGRAPHER: Linda Werner
~~KAY WALKER~~

DATE OF PHOTOS 7-19-93

FILE NO(S). A51-00113, A51-02061



POD #2
Located in
SE NW, S26,
T11S, R9E
cement stand-
Flume had
been washed
out.

Headgate to
Ditch from
POD #2



Green - A51-00113
Red = A51-02061

No Gov't Lots on this property -

SUB IRRIG From line up.

ASCS has
aerial photos
of irrig.
lands.

115

BLM
ground

pld

pld
flume
washed
3 yrs ago -
will be
rebuilt

9E

CC15 (1979)

(1979) CC16

NAPP CC16 NW
7-12-87


115-9E-S15, 22 & 23




A51-00113 & A51-02061

CC15
(1979)

CC16
(1979)



NAPP CC16 NW
7-12-87



④



PHOTOGRAPHER: Linda Werner
~~RAY WALKER~~

DATE OF PHOTOS 7-19-93

FILE NO(S). A51-00113, A51-02061



Place of Use — taken looking north to
northeast. See pg. 3 also

