

29-07154

POD

FIELD EXAM: 7-30-02



Looking SW at Point of Diversion pump house. Licensing field exam seems to indicate that well is outside of pump house. However, FE doesn't confirm this. No signs of well in surrounding area. Must be inside structure (csaxton 8/7/02).