



From claim file A24-04016 (Rock Creek)



Hartman Irrigated Lands - Field Inspection 2005



Contor_gps_july05.shp

□ Other

○ POD

△ POU

A24_04015_ponds.shp

All_hartman.shp


PLSS Section LinesGcdb_sections.shp

Gcdb_qq.shp

1987 Aerial Photo from Idaho Department of Water Resources.

Illustration by Water Resources Field Services 208 681 9100

Hartman Irrigated Lands - Field Inspection 2005



Contor_gps_july05.shp

□ Other

○ POD

△ POU

■ A24_04015_ponds.shp


■ All_hartman.shp


■ PLSS Section LinesGcdb_sections.shp
Gcdb_qq.shp



2004 Aerial Photo from Monte Clemo, Georeferenced by Water Resources Field Services.
Illustration by Water Resources Field Services 208 681 9100

Hartman Irrigated Lands - Field Inspection 2005







y
vice