





①

POND #1
-View From Downstream
SIDE OF DAM.
NOTE Culvert which
spills WATER
to RIVER.




② Looking Southwest
From DAM of POND
① to point where water
enters RIVER



③ Corrugated stand pipe in
POND 1, LEADS to horizontal
DISCHARGE pipe.

MICROFILMED
APR 15 1994




④ View of Pond 1
From Southwest
corner of Dam
Near Bank of Little
Lost R.

Pond 2 in
Background




⑤ Inflow to
Ponds 1-3
& Pond 3 in
Background.

View is From
Road looking South




⑥ Ditch Along Road
which runs east-west
to Ponds 1-3, and
Ponds 5-8.

MICROFILMED
APR 15 1994



(7) View of Pond 5 From DAM. W/ WELL Discharging Water to Pond, Culvert to Pond 7, AND Sluiceway Spilling Water to Pond 6.



(8) Looking South From DAM ON POND 5; POND 6 in ~~at~~ FOREGROUND & POND 8 in BACKGROUND.

NOTE: Culvert connecting POND 5 to 6 & SLIDE GATES in POND.



(9) Looking Southwest From POND 5; POND 7 in BACKGROUND. Flow From POND 5 to POND 7 in FOREGROUND.

MICROFILMED

APR 15 1994




Photo 1. Big Spring Creek

DIVERSION. NOTE THE THREE DIVERSIONS.

THE PIPELINE DIVERSION WAS INSTALLED ABOUT AUGUST 1995. DELIVERS WATER DIRECTLY TO THE POND SHOWN IN PHOTOS 4, 5 & 6.

THIS POINT OF DIVERSION IS LOCATED AT: SENWISW SEC. 5 T. 7N., R. 28E.



Photo 2. A WESTERLY VIEW OF THE THREE DIVERSIONS IN Photo 1.

NOTE THE BURIED PIPELINE TRACE. THERE ARE NO OUTLETS OR DIVERSIONS FROM THIS PIPELINE.



Photo 3. Little Lost River DIVERSION FOR WINTER USE. CONVEYANCE TO THE PLACE OF USE IS BY OPEN DITCH.

THIS POINT OF DIVERSION IS LOCATED AT: NESW 1/4 SEC. 12 T. 7N., R. 27E.

SAGE WILLOW PNC.
A33-02133

Photo taken: 14 Nov 95 ABR

LOOKING NORTHERLY




Photo 4. Shows THE BIG SPRING CREEK PIPELINE DISCHARGE TO THE POND AT: SEENSW SEC. 7 T. 9N., R. 2BE.

LOOKING SOUTHWESTERLY



Photo 5. Shows PIPELINE DISCHARGE TO THE POND AND APPROX. LOCATION (IN RELATION TO) OF POND DISCHARGE

LOOKING NORTHEASTERLY




Photo 6. Looking NORTHEASTERLY ACROSS THE POND. SHOWS INLET AND OUTFLOW STANDPIPE.

SAGE WILLOW, INC.
A33-02133

Photos taken: 14 Nov 95 ABR