

WA

RECEIVED

MAY 17 2010

DEPARTMENT OF
WATER RESOURCES

Memorandum

Date: May 13, 2010

To: Monica Van Bussum

From: Bob Foster


Re: 75-14601 (Hutchings) — *SRBA ordered amended PD for 75-14598*

On May 13, 2010, I made an on-site visit to property owned by Marvin Hutchings. The purpose of this visit was to verify water use for 75-14601.

The delivery system for 75-14601 consists of a wooden structure at the point of diversion on Twelve Mile Creek. A ditch runs along the north side of the POU that lies on the east side of Hwy 93. The ditch could be checked up to allow water to flow to the south on the east POU.

This ditch runs approximately 390 feet from the point of diversion in a westerly direction and then goes under Hwy 93 through a large culvert. There is a concrete check structure on the west side of the highway that can divert water into a ditch that runs south to north along the POU on the west side of Hwy 93. This ditch could be checked up to allow water to flow to the west to irrigate the POU west of Hwy 93.

No water was being diverted at the time of my visit and it does not appear the ditches have been used in recent years. The land has been cleared some time in the past and with the evidence of the ditches on the property it would appear there has been historical irrigation on this property.




2004



Concrete check structure on west side of property at HWY 93 culvert. 05/13/10



East side P111 looking east from HWY 93 Culvert Ditch on left side of P111 05/13/10



West POU looking north from Hwy culvert 05/13/10



Looking North at ditch on west side of HWY 93. POI left of ditch 05/13/10

Culvert for ditch under HWY 93 05/13/10





Culvert under Hwy 93 for ditch 05/13/10



POD roof old ditch approx. 309 feet east on Twelvemile Creek road. 05/13/10

Jitch on eastside POU. Ditch runs East to West along North side of POU. 05/13/10

