



Galloway Photo #2



2088








Galloway Photograph Log

Photograph #	Comments
1	Trough shown in foreground, shut-off valve in top center; note weathering of concrete
2	Trough in lower right showing pipe in lower part of photo, shut-off in left center
3	Looking downslope to trough, photo point is on top of cistern
4	Photo of crustose lichen imbedded in the concrete with scale
5	Photo of crustose lichen imbedded in the concrete

gallery

- Mapall
 - Wells
 - Point of Diversion
 - Place of Use
 - Major Rivers
 - Major Roads
 - Streets
 - Areas of Drilling Concern
 - Contamination Area
 - Nitrate Priority Areas
 - Critical Ground Water Areas
 - Ground Water Management
 - Cities
 - Townships
 - Sections
 - PLSQQ
 - Counties
 - Eastern Snake Plain Aquifer
 - Adjudication Photos
 - 2000 NAD83



⊗ - Approximate location point of diversion and use.

St. Maries, Idaho
April 4 2011

To whom it may concern:

Kelsey & Stanley Galloway:

In June, 1966 livestock water was needed. At this time a spring on (Kelsey & Stan property current owner) was developed. This consisted of tapping a natural spring, building a 6' X 8' concrete storage reservoir and concrete stock watering trough. This was used for that purpose until the property (about 1990) was converted to a tree farm. Since then the system has been used for irrigation of tree seedlings, in addition to the previous uses for wildlife, & fire protection.

Raleigh A. Hughes
Ardys Hughes
Raleigh & Ardys Hughes,
Parents Of Kelsey Galloway