

RECEIVED

AUG 20 2013

IDWR / NORTH

August 20, 2013

Statement Regarding location of Point of Diversion for License 94-7259

License 94-7259, issued to my father Kenneth E. Harmon, has an error concerning the legal description for the Spring that serves as the Point of Diversion. The License and Field Exam improperly state that the spring is located on property tax parcel 47N02W-19-9200 (Township 47 North, Range 02 West, Section 19, South East South East).

The correct location for the Spring that serves as the source of water for License 94-7259 is on property tax parcel 47N02W-20-5500. This property is owned by Roy E. Mortensen and we share use of the Spring. The correct legal description for this property is (Township 47 North, Range 02 West, Section 19, South West South West).

The location for the spring that has been used for License 94-7259 has never changed during my ownership or father's ownership. My father applied to establish the water right in 1983.



Mr. Warren J. Harmon
29894 S Bow RD
St. Maries, ID 83861

SCANNED

AUG 20 2013