

FIELD EXAMINATION OF CSRBA WATER RIGHT CLAIM

Claim Identification Number: 91-7502

Date of Examination: 03/01/2016

Approximate Time of Examination: 10:25 am

IDWR Field Staff: Evan Roda

Point of Contact: Steven O. Geike (208) 282-8546

Examination Location: 1955 E Round Lake Rd, St. Maries, ID 83861

Purpose of Visit: Locate claimed points of diversion (2 wells) and mark with GPS

Field Examination Notes: Met with claimant Steven Geike at location of claimed water use. He first showed me the location of the original well on the property (3). Mr. Geike explained that the well had produced only a small volume of water and was insufficient for their domestic use requirements. Mr. Geike then took me to the newer well (4), which was drilled to supplement or replace the old well. He explained that the new well was connected to the home shortly after he and his wife purchased the property about three years ago, and the old well was subsequently disconnected. The observed place of use includes one home and lawn and garden areas around the house (1, 2). Water use appears to be within de minimus domestic use requirements.

A Garmin GPSmap 60CSx handheld GPS was used to accurately locate the two wells, utilizing an average of 100 points for minimal positional error. Both wells are located within the NE ¼ of NE ¼ Lot 1, T 46N R 03W Sec. 4.

Original Well Location:	N 47° 22.201'
(Accurate within 13.7 ft)	W 116° 42.909'

Replacement Well Location:	N 47° 22.177'
(Accurate within 11.0 ft)	W 116° 42.949'

SCANNED

MAR 01 2016



1) Place of Use – Home



2) Place of Use – garden and plantings on north side of house



3) Point of Diversion – Original Well



4) Point of Diversion – Replacement Well

SCANNED
MAR 01 2016