

no drilling permit
IDAHO DEPARTMENT OF WATER RESOURCES

RECEIVED

NOV 06 1996

WELL INSPECTION FORM

Department of Water
Southern Region

CPS#

Site Tag # - A 0003780

1. DRILLING PERMIT NO: None OTHER APPLICABLE NO: 36-08305

2. OWNER: Aardena's Heida Dairy Phone: (208) 536-2187
Address: P.O. Box 140, Weiser, ID 83355

3. WELL LOCATION: Twp 6S, Rge. 1E, Sec. 11, NW 1/4 SE 1/4
County Gooding (Provide sketch map and photo on reverse.)

4. DRILLER: _____ Lic. No. _____
When Drilled? _____

5. WELL CONSTRUCTION:
Casing Diameter _____ inches Water tight cap? ☐ Yes ☐ No Access Port: ☒ Yes ☐ No
Casing $\geq$ 12 inches above ground? ☐ Yes ☐ No - Describe _____
Depth of Casing unknown ft. Method Drilled unknown
Condition of Well Casing: ☐ Good ☐ Fair ☐ Poor Describe NOT SEEN
Control Valve? ☐ Yes ☐ No Pressure Gauge: ☐ Yes ☐ No
Condition of Piping and Valving _____
Auger to a depth of visual ft. Evidence of Annular Seal ☐ Yes ☒ No
Are there obvious construction problems that may be a source for contamination or waste of water?
☒ Yes ☐ No (Describe in Remarks and Attach Photo - On Reverse)

6. HYDROLOGIC INFORMATION:
Depth to Static Water _____ ft. Water Temperature N/A °F
Flowing Artesian ☐ Yes ☒ No Pressure: N/A (psi)
Water Sample Taken? ☐ Yes ☒ No If yes, describe purpose _____
Water Quality Measurements/Observations (Describe) _____

7. WELL USE:
☐ Domestic ☒ Irrigation ☐ Stock
☐ Test ☐ Municipal ☐ Industrial
☐ Abandoned ☐ Waste Disposal/Injection ☐ Not Used
☐ Other: _____

8. POSSIBLE CONTAMINATION SOURCES:

Is there evidence of Chemigation? ☐ Yes ☒ No

If yes, is there a check-valve present? ☒ Yes ☐ No

Is there a possible source of contamination nearby? ☐ Yes ☒ No

If yes, what Type?



How far away from the well is this source?

9. REMARKS: The sand from the field has blown and filled in around the pump. Therefore, ground level has raised to the level of the openings in the pump housing. The filter screen is located in the pump housing without a screen cap. This would allow rain or snow to enter the pump housing and enter the well.

Daniel R. Nelson Summer Field 2017
Signature of Dept. Representative & Title

8-12-96
Inspection Date

PHOTOS, DRAWINGS, OTHER ATTACHMENTS:





THESE ARE PICTURES OF DIRT FILL-IN AROUND PUMP.
 WITH OUT A CAP ON THE ACCESS PORT & NOW OR DIRT COULD
 FILL INTO OPENING OF PUMP. THERE IS LESS THAN 2"
 CLEARANCE FROM GROUND TO PUMP VENT.

