

SVR #7 End-of-Test Detailed Plot Showing IDWR's "Missing Data" Caused by Water in Pump Column Flowing into Aquifer after Pumping Stops

