

East side of Rd

Pic<sup>#</sup> 1 tanks looking East 2 tanks Approx 9/19/07 - Field Notes

Pic<sup>#</sup> 2 & 3 Broken pipe 150' Approx E of tanks

1 1/2" PVC pipe into a 2" OD Steel pipe

Pic<sup>#</sup> 4 Source <sup>looking S</sup> Pic<sup>#</sup> 5 West from Source toward Broken pipe

Source to Broken pipe 75'-100' ft

Jeff is the Approx location of the PVC into the steel pipe  
to the west of Source

did not locate inlet into tanks appears under ground

tanks appear to be plumbed together under ground 1 1/2" pipe

the tanks are not actively taking water no piped over flow

tanks are Approx 8' long 3' wide 2 1/2' / 8' x 3' x 2'

5' dia cylinder possible bottom drain

~~3/12/07~~  
J. Walker

9/19/07