

M E M O R A N D U M

Date: June 28, 2004
To: Water Right File 25-7643
From: ERetelle
Re: recommendations

Field examiner failed to make recommendations for flow rate and volume but enough information was given in the report to calculate these values. Using the flow rate chart from appendix 4 of the field examiner's handbook, flow rate was calculated to be .18 (same as permit) and volume was set at 9af (14 homes and 1 office, internal use only).

M E M O R A N D U M

Date: June 28, 2004
To: Water Right File 25-7643
From: ERetelle
Re: amendment

Permit showed both PoD and PoU in the SESE. ArcView and the field exam map both show both in the SWSW. Field examiner also mistakenly put the PoU in the SESE. These errors have all been corrected by the amendment.