



IDAHO DEPARTMENT OF
WATER RESOURCES

BRBA FIELD EXAMINATION REPORT

Claim Number: 11-7583

Exam Date: 7/01/2026

Exam Time: 1:20 PM

IDWR Staff Present: Brian Wunsch, Jose Pacheco, Brent Bonney, & Christian Stewart.

Claimant/Representative Present: Access granted by claimant over the phone.

☒ **No**

☐ **Yes**

Exam Location: Northern half of 12S 43E 35 NWSE.

Examiner's Signature:

Purpose of Exam: Confirm elements of claim, focusing on diversion works and potential POU.

Conclusion of Exam: No use was found, diversion works and irrigation system were dilapidated, and physical features do not allow for the irrigation of the claimed POU.

Exam Narrative:


Starting at the above-ground concrete cistern (Photo 1), it was clear that the system had not been in use recently. There was no water present in the system (Photo 2), and it was unclear how water was put to use in the past. The open channel downstream of the cistern was dry (Photo 3).

The land Southeast of the cistern is the claimed POU. Looking South, this land is hilly and slopes upward from North to South (Photo 4). Looking Southeast, the land slopes downward from West to East (Photo 5). Looking Northeast, the land flattens out and slopes downward gently from West to East (Photo 6). The claimed POU would be difficult to impossible to irrigate with the system as described and understood.

The last set of photos were taken in the field where the channel crosses through. This area is not within the claimed POU. The photos were upslope (Photo 7), downslope (Photo 8), and of unused wheel line parts (Photo 9).

An active recommendation for irrigation cannot be recommended in any capacity. This has been confirmed through the field exam.

Photos:







☉ 177°S (T) ☉ 42°20'6"N, 111°23'34"W ±13ft ▲ 6103ft



☉ 117°SE (T) ☉ 42°20'6"N, 111°23'34"W ±26ft ▲ 6102ft



☉ 74°E (T) ☉ 42°20'6"N, 111°23'34"W ±9ft ▲ 6092ft



