

RECEIVED

MAR 22 1999

Department of Water Resources

COMMUNICATION DOCUMENTATION

IDWR Employee/Agent Georgia Satterlee

DATE
March 8, 1999 1:54pm

CUSTOMER
Steed/Sundberg

SUBJECT: 43-07322
phone call (.) walk-in (.) other (x)

I met with Dave Sundberg and Garth Steed. The new structure still isn't up to par. See photographs. The items that will be corrected:

1. The rectangular weir will have a crest length of 2.0'.
2. The fall distance seems to be acceptable, however the structure was leaning downstream and it will be necessary to plumb it up.

Amongst the discussion for this structure, Dave brought up the inadequacy of the downstream structure. When the above items were clarified, I then said to Dave, "The last time we met, you did not have a problem with the downstream structure." He began saying that the Water District has spent hundreds of dollars on this one problem. I replied with, "That is why we are here and discussing the solutions." He said the boards were taken out and they should be replaced to make the weir accurate (when the boards are replaced the weir would be a broad crested weir?). I believe replacing the boards is not a major deal.

We are going to meet again 15 March 1999 @ 1000 hrs., to verify if the upstream device is acceptable. Most likely hash over the downstream device.

1/2



Georgia Satterlee
08 Mar 99 10:30 hrs.

Photos should be dated 08 Mar 99

photo looking NE'ly from farm rd

Farm Rd →



photo looking SW'ly

2/2



Georgia Satterlee
08 Mar 99 1030 hrs.

upstream
New diversion structure



Photos should
be dated
08 Mar 99

