

RECEIVED

SEP 20 2011

WATER RESOURCES
WESTERN REGION

Iron Horse Ranch, LLC
11204 N. Bar 21 Dr.
Glenns Ferry, Idaho 83623
(208) 366-7931

September 12, 2011

Cold Springs - Bennett Creek Water Dist.

Last week when Teresa received a copy of the Water masters report for the annual meeting I was surprised to learn that in the opinion of the Water master we are in "Non-Compliance".

1. We have two Magnetic flow meters.
2. Both lines are lockable.
3. The in stream weir was repair as we stated it would be. However, the ditch washed out again. At which point it was no longer used. Before use we will repair the system.

The water master states that "Harley was happy", well I want to be happy too! When a water master has an issue he should contact the person at that time regarding any concerns. So that way a person could meet with him to explain the system, or correct it if needed. Why there was fluctuation in the flow meter, I don't know maybe it had an air bubble. However the pipe is always full.

As the Water master states "With the creek essentially dry it seems a mute point". With the water master being mute at the time it does not allow for the issues to be resolved.

respectfully submitted,



John B. McCallum