

Field Exam Summary A25-02022B 20 November 2003

Bryce Contor

Water Resources Field Services

General Comments, A25-02022A, A25-02022B, A25-02047

See image "A25-02022A_A25-02022B_A25-02047_Notes.jpg" for a copy of field notes. The field notes refer to UTM coordinates for GPS readings for scaling on a USGS map, but the reported GPS points are converted to IDTM. See paper file A25-02022A for photos and the map guide to photos. Photos on the CD are identified as "A25-02022A_A25-02022B_X.jpg" where "X" is the photo number or numbers (some are scanned 2 photos per image) or "A25-02022A_A25-02022B_A25-02047_9.jpg" for the last photo.

These rights are related by source, location and ownership. Original licenses A25-02022 and A25-02047 were both from Seventy Creek and served adjoining lands. A25-02022 has been split by an ownership change but the owners of A and B have a family relationship. Benjamin Hunter, the claimant of split "A" is a brother to Mrs. Butler, the claimant of record of split "B." The Butler property is now owned by a partnership of Butler children. I spoke to one of the daughters on the phone and mailed a change of ownership form but I have misplaced my notes. A25-02047 is claimed by Benjamin Hunter, claimant of A25-02022A.

I met with Mr. Dalton, Mr. Passey, one of Mrs. Butler's daughters who I think is Mrs. Passey, and a young man whose name I didn't record. Mr. Dalton said he is Mr. Hunter's son-in-law and Mr. Passey said he is Mrs. Butler's son-in-law. The young man is Mr. Dalton's son-in-law.

The split of ownership appears to be correct. Part of the original POU of license 25-02022 is still in use, and includes parts of A25-02022A and A25-02022B. There has been an accomplished change in source to include some use of a spring that is tributary to the licensed stream, Seventy Creek. This includes an accomplished change in place of use. This is for the irrigation of a lawn and garden that is a few hundred feet from the original place of use.

Part of 25-02022 and all of 25-02047 were served by a ditch which all the individuals confirmed has not been used for many, many years. When they've tried to use it, it generates a wetland and the water never gets past the wetland. Photo 9 shows this part of the POU of 25-02022 and the POU of 25-02047.

Note that the license papers originally supplied are from the wrong license. I have left these in paper file A25-02022A and added the correct microfiche copies from IDWR Eastern Region.

General Comments, A25-02022B

This right has a small part of the irrigated pasture POU that shares the POD of A25-02022A. It also has a lawn and a garden POU that use a spring POD which is an accomplished change in source. The spring is a tributary of the original source. The owners are planning to come to IDWR to amend the claim and to file stockwater claims.

Ownership

I mailed a change of ownership form, but I have lost my notes. The new owner is a partnership with the same mailing address as the current claim.

POD

Two POD. One is the creek POD shared with A25-02022A, waypoint 84, IDTM 678,697E 235,418N. The second is the spring POD that serves the lawn and garden, waypoint 85, IDTM 678,526E 235,401N.

POU

See sketch on layout in A25-02022A. See change of ownership papers to correctly locate property line between the two rights.

Overlap

POD shared w/ A25-02022B.

Conflict

None noted.

Priority

March 25, 1910 per license.

Quantity

Per license, 0.02 cfs/acre for acres identified w. GIS.


Water Use

Irrigation confirmed. Stockwater and domestic also found. Claimants may amend claim or file additional claims.

List of Photos

See prints of photos in paper file A25-02022A with descriptions.


Bryce A. Contor


Date