

A25-04167 Summary 8/28/03

- 1) Ownership: Appears to be correct. Claimant Tebbin Johnson is resident.
- 2) POB - See sketch on Layout. Claim description appears to be correct. GPS 663164 E, 271340 N, waypoint 4167. This is a replacement well, drillers' tag D0026658.
- 3) POB - see sketch on Layout. Per Mrs. Tebbin Johnson, the back part of the North home lawn and the lawn around the middle home are watered from the well, the rest is flooded from the canal. Mrs. Johnson was in a hurry & didn't mention the trees but since the trees are drip irrigated I presume they are ir. from the well.
- 4) Use of Water - 4 homes, shop & cellar, Corvalls not currently in use but probably were at time of claim.

A25-04167 Summary p 2

- 5) Priority. Affidavit Supports 12/31/1929.
- 6) Capacity. Did not find motor controller - Mrs. Johnson had to leave. Claim < 0.20 cfs.
- 7) Photos 1 of well, 1 of lawn. Photo of trees failed.

Dwight A. Connor

A25-04167 Field Insp. 8/28/03

Visited w/ Mrs. Tebbin Johnson.

GPS 663,164 E 271,340 N Waypoint 4167
replacement well, driller's tag D0026658

Photos - 1 of well, 1 of lawn behind brick home,
1 of trees w/ drip irr.

Per Mrs. Johnson most lawn is irr from
canal. Around the middle home (behind
the brick (North) home is too high & these
are watered from well. Mrs. Johnson
didn't mention trees but because of
drip I assume they are watered from
well.

Mrs. Johnson states water use is 2 hours
year round, 2 hours summertime only,
slip & potato cellar. Coralls at PCA
indicate historical usage for stockwater,
probably stockwater use was current as
of claim date. Besides documentation
in file, Lin Johnson confirmed this (4167)
water use during interview for A25-4168.

Mrs. Johnson was in a hurry to leave
so I didn't receive pump controller info,
Shee claimed cts < 0.20

Contact Log A25-04167

8/25/03 13:38 522-8168 (Lin Johnson #)

Mr. Johnson - Thursday

Access fr. Cherry Glass 1/4 mile S.

just S. of RR. Branch - Double-wide -

Appointment late AM or early afternoon

8/28/03 524-2788 (Tebbin Johnson)

phone call got a FAX machine.

field inspection w/ Lin Johnson was for A25-4168.

Tebbin is who I need to contact for A25-4167



IDAHO DEPARTMENT OF WATER RESOURCES

SNAKE RIVER BASIN ADJUDICATION - BASIN 23-27



Invoice #

2000-055-23-27-0

RIGHT ID 25 4167
POD ID 174580
Folder No. A2504167
Claim Status In Use
IDTMEAST 663190
IDTMNORTH 271324
GPSID A0009395

Diversion Description

WELL/PUMP/PRESSURE TANK.

Assumptions

Horse power, pressure head, and elevation head.

Phase-0 (No Attention)
Phase-I (Ready to Go to Field)
Phase-II (Site Visit - Data Missing)
Phase-III (Complete w/issues)

Linked Photos\25-4167-001.JPG

Photos Photos\25-4167-002.JPG

GPS Accuracy (ft)

17 Feet

Date (M/D/Y)

07-25-02

Time

17:15

Flow Rate (CFS)

0.16

Open Channel Flow

☐ Complete one box from both Area and Calculation sections

Cross Sectional Area

☐ Circular Channel

- ☐ Less than half full
☐ Half full
☐ More than half full
☐ Full

Diameter 0

Depth 0

☐ Rectangular Channel

Width 0

Depth 0

Flow Calculation

☐ Continuity

Velocity

0

☐ Orifice

(Use only for head over a pipe flowing full with free discharge)

Depth of Water above orifice centerline 0

☐ Weir

(Use only for water flowing freely over weir)

Height of water above nappe 0

Width of weir 0

☐ Manning (If used, include photo of representative channel section)

Channel Slope

Channel Description

Concrete lined .016
Smooth earth .025
Earth .033
Rough bed, weeds on sides .04
Smooth natural stream .033
Rough natural stream .1

Pumped System ☒

HP 3

Pressure Head (psi) 30

Elevation Head (ft) 50

Motor Mfg

Motor Serial #

Pump Type Submersible

Pump Mfg

Pump Serial#

New Contact Information ☐

New Contact Comments

This Form and the associated query are the exclusive intellectual property of Intrepid Technology Resources Inc., and may not be copied, modified, or distributed without the express written consent of Intrepid Technology and Resources, Inc.



intrepid technology & resources
incorporated

FOLDER NO.

A2504167