

Donald Hall

29-4160.

Spring - Sinks.

Purchased Property: Mom & Dad 1962, 1986 - Don & Debra.
gone back to ditch about 10 yrs ago when
the catchment washed out. The County
was maintaining the catchment but has stopped.

POD change: The springs come from to catchments in
section 28, they come together into a single ditch.
IT'S diverted from the ditch in the NW of section 27.
and Not in NE of section 28. IT'S always been
this way even when Donald C. Hall owned the property.

POU: Around the creek the water subs, they still
irrigate the same property.

POD HALL SP N42°42.410' W112°14.850'
8/22/02 9:40 AM (10:40 AM)

1 Photo taken looking East at First Spring

1 - Photo looking Southwly at 2nd Spring

