

02/18/2003

allen

NOTICE OF ERROR
REPLY

Please type or print clearly, fill out this form completely and mail.

Return this reply form to IDWR by the deadline date printed below if you want IDWR to change your recommendation or you want to let IDWR know that you agree with its recommendation.

YOUR DEADLINE FOR RETURNING A NOTICE OF ERROR REPLY IS: April 21, 2003

Water right number: 29-2044E

BARBARA A SMITH
5731 S OLD HWY 91
MC CAMMON ID 83250
Telephone Number: (208) 254-9319

RECEIVED
APR 28 2003
Department of Water Resources
Eastern Region

1. Describe the portion of the proposed recommendation with which you disagree (e.g. priority date, period of use, source):

I have more than 5.8 acres that should get water from the Lewis-Goodenough ditch (1904)

2. Describe the changes you wish to make in the proposed recommendation:

I bought 1 inch of water per acre of the "Exhibit A"

3. Give a brief explanation as to why you disagree with these portions:

Exhibit A shows more than 5.8 acres of water rights.

☐ I AGREE with this proposed recommendation: no changes need to be made.

DATE: April 20, 2003 SIGNATURE: Barbara A Smith
Please print your name: Barbara A Smith

IDWR Regional Office, 900 N Skyline Dr Ste A, Idaho Falls, ID 83402, 2085257161

10/25/01 Field Exam AND Discussion w/ Claimant (see notes in 29-7609

GPS OR PULL shows 5th Ac, A recommendation @ 0.02 cfs/ac

EXHIBIT "A"

A parcel of land situated in the Northeast quarter of the Southeast quarter of section 35 and the Northwest quarter of the Southwest quarter of section 36, township 8 South; range 36 East, Boise Meridian, Bannock County, Idaho, more particularly described as follows:

Commencing at the East quarter corner of section 35, said point being marked by a Bannock County brass cap stamped L.S. 968; thence North $89^{\circ}50'44''$ West along the latitudinal centerline of said section 35, 350.00 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $0^{\circ}13'12''$ West, 350.97 feet to the true point of beginning, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence continuing South $3^{\circ}06'15''$ West, 144.93 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $28^{\circ}52'00''$ East, 321.72 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $11^{\circ}25'29''$ East, 316.48 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $8^{\circ}10'08''$ West, 63.21 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $89^{\circ}50'44''$ East, 199.39 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $8^{\circ}51'21''$ East, 176.71 feet to the South 1/16th line of said section, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $89^{\circ}56'09''$ East along said South 1/16th line, 285.19 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence North $16^{\circ}54'44''$ West, 240.18 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence North $83^{\circ}50'00''$ West, 132.39 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence North $1^{\circ}44'50''$ West 43.79 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence North $22^{\circ}23'21''$ West 81.09 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence North $3^{\circ}48'54''$ East 116.83 feet, said point marked by a 1/2 inch iron pin tagged L.S. 968; thence South $72^{\circ}25'52''$ East 146.48 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence North $1^{\circ}52'30''$ East 316.31 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $89^{\circ}20'10''$ West 286.93 feet to the East line of Section 35, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence North $0^{\circ}13'12''$ East along said East line 228.22 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence North $89^{\circ}50'44''$ West 350.00 feet to the true point of beginning.

Excepting therefrom the following described parcel:

A parcel of land situated in the Northeast quarter of the Southeast quarter of section 35 and the Northwest quarter of the Southwest quarter of section 36, Township 8 South, Range 36 East, Boise Meridian, Bannock County, Idaho, more particularly described as follows:

Commencing at the East quarter corner of section 35, said point being marked by a Bannock County brass cap stamped

L.S. 968; thence North $89^{\circ}50'44''$ West along the latitudinal centerline of said section 35, 350.00 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $0^{\circ}13'12''$ West 350.97 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence continuing South $3^{\circ}06'15''$ West, 144.93 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $28^{\circ}52'00''$ East, 321.72 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $11^{\circ}25'29''$ East, 116.48 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $8^{\circ}10'08''$ West, 63.21 feet, said point being marked by a 1/2 inch iron pin tagged L.S. 968; thence South $89^{\circ}50'44''$ East, 199.39 feet; thence South $8^{\circ}51'22''$ East, 94.00 feet to true point beginning of exception; thence continuing South $8^{\circ}51'22''$ East 19.87 feet; thence North $31^{\circ}57'34''$ East 118.22 feet; thence North $21^{\circ}26'00''$ East 85.15 feet; thence North $1^{\circ}44'50''$ West 43.79 feet; thence North $23^{\circ}23'21''$ West 81.09 feet; thence North $3^{\circ}43'54''$ East 116.83 feet; thence South $88^{\circ}17'36''$ West 24.15 feet; thence South $1^{\circ}54'50''$ East 115.5 feet; thence South $20^{\circ}57'29''$ East 99.38 feet; thence South $21^{\circ}26'00''$ West 99.53 feet; thence South $28^{\circ}17'28''$ West 105.28 feet to the true point of beginning of the exception.