

29-02046A Lic.

I. Amended to be claimed as Licenses. However, there have been changes to roadways since 1906 (Priority Date). Examiner's map tends to show use in the area that would now be on the West side of Old Hwy 91, not shown today. In addition, Claimant Amended Photo (Contractor copy) to include the East Hillside -

25m → IT IS NOT irrigated as per Field Exam 10/10/01. $\Rightarrow$ CP 25 AND COUNTY OWNERSHIP THOMAS DOES NOT SHOW 25 AC AMENDED.

II. Original License calls source as So. Fr. Bill Jackson Cr.; Claimed as Grobn Canyon Cr.

Reference is made to OQ AA-91; source

stream is called Grobn Canyon Cr. $\Rightarrow$ CP 2

(Δ FROM Lic NAME TO USGS RECOGNIZED NAME.)

The POD has also been changed way prior to

1987 and is not as claimed in NWNWSW Sec. 26.

Grobn Canyon Cr. does not flow through this QD.

Rather POD is located at SE SW NW Sec 26 $\Rightarrow$ CP 3

III. Q Lic. as 0.5 cfs. Adjusted accordingly @ 0.02 cfs per irrig acre. $\therefore$ 13.5 ac $\times$ 0.02 = 0.27 cfs, making

0.23 cfs lost to FORFEITURE/ABANDONMENT, RE: 42-221(2)

$\Rightarrow$ P 4 Remark CONDITION PRIOR TO 1976 RE: OQ AA-91 and TC.

Claim Invest Handbook 1/13/1999 (DRAFT) Chp. 10,

FORFEITURE AND ABANDONMENT: Parts III-V.