

Danskin Ditch Co.
762 W. Hwy 39
Blackfoot, ID 83221

RECEIVED


MAR 16, 2006

DEPARTMENT OF
WATER RESOURCES

Idaho Department of Water Resources
322 E. Front St.
P.O. Box 83720
Boise, ID 83720-0098


To Whom It May Concern:

The Board of Directors of the Danskin Ditch Company has deemed that the service area boundary of the Danskin Ditch Company is illustrated accurately, without modifications, and in its entirety on the map(s) created by Danielle Favreau on February 8, 2006. Additionally, the previously identified map(s) accurately illustrate the location of land serviced by the company as of 1987. We understand that in the process of finalizing the SRBA recommendations, these maps may be adjusted.



Neil Morgan, President

2-28-06
Date



Delwin Bevan, Vice President

2-23-06
Date



Kim Cox, Board Member

2-22-06
Date




Gene Adams, Board Member

2-22-06
Date



Ron Ellis, Board Member

2-22-06
Date



Danskin Ditch Co.
Draft Service Area Boundary
& Irrigated Acres

0 0.125 0.25 0.5 0.75 Miles

LEGEND

Townships	Service Area Boundary 5824 Acres
Sections	Irrigated Acres 5158 Acres
Quarter Quarter	Imagery 1987/1988 NAPP

Prepared by: Danielle Favreau, 2/6/06, IDWR/NMRI