

5/24/02 : 1-800-237-8535 - Tulkom

Ronda is office Manager.

: Called and left Message to Call Back : 4:15

5/28/02: Craig Pulvan - Field Exam - Setup by Phone

5/29/02 : Look up 29-07855 - license that I don't have
OK { on Record. licensed for 0.67 cfs + 438.5 AP
capacity of 0.720 cfs according

: Look up 29-07151 - 1973 - Permit - look if lapses
says well #3

: Total of 4 wells + River Pump.

All pump into a Common System into a tank. Unknown size

: James

: ~~James~~ Showing me the System - Been Here Since 1984

: #1 10 horse Seibersville
Gouge 5" C10010640
Replacement last Fall 100' deep
100-200 GPM

643182
189352

#3 7.5 HP Franklin
Grundfos 80375-B
Supplier with Rebuilding only
~ 100-150 GPM

River Pump Intermittent 3 or 4
Tsurumi months out of
KTV-37 year, River only

5 HP Sump pump
designed to run 150 GPM
~ 132 GPM
100 GPM

#250-260 GPM

#2 10 HP Franklin 112
Grundfos 150S100-05 ~ 35 ft A
100 GPM ~ 50'

#4 Unknown 700' deep Pump
5 GPM Drinking Water 175' deep
400-550 model
7-17-00 - Amps 8.9

Flow Meter McCrometer

350

SV 234-3275-202
PH/AZ 60

Volt 460

Storage Water tank

~ 19.5' Ft diameter

8" x 8' 8" = 24'6" high.

B/W 102+Pant
350 GPM



Subject

~~12/15/02~~ 5/29/02

System Diagram

Date

Sheet

of

Job

By

Chkd.

