

29-7239.

POD change ; when?

2pts of Diversion. IN SWSE of Sec. 33; T6S, R39E.

Claimed. SWSE & SESE of Sec. 33; T6S, R39E.

When did change occur? No change, these are the original
system. wells. Report puts

POU changed?

License	6S	39E	34	SWSW	1 ac.	} 37
	7S	39E	3.	L-2	25	
				NWSE	11	

Imagery doesn't agree. verify