

12/18/2006

NOTICE OF ERROR
REPLY

RECEIVED

JAN 03 2007

DEPARTMENT OF
WATER RESOURCES

Please type or print clearly, fill out this form completely and mail.

Return this reply form to IDWR by the deadline date printed below if you want IDWR to change your recommendation or you want to let IDWR know that you agree with its recommendation.

YOUR DEADLINE FOR RETURNING A NOTICE OF ERROR REPLY IS: 01/05/2007

Water right number: 37-2623

THE VALLEY CLUB INC

PO BOX 252

SUN VALLEY ID 83353

Telephone Number: (208)788-0997

1. Describe the portion of the proposed recommendation with which you disagree (e.g., priority date, period of use, source):

Place of use

2. Describe the changes you wish to make in the proposed recommendation:

Acreage recommended is 120.7 acres

*Change To 143.8 - See Brockway Engineering
.shp file and spreadsheet*

3. Give a brief explanation as to why you disagree with these portions:

IDWR .shp file is incorrect

☐ I AGREE with this proposed recommendation: no changes need to be made.

DATE:

12/29/06


SIGNATURE:

Charles E. Brockway

Please print your name:

Charles E. Brockway

IDWR Regional Office, 322 E Front St
PO Box 83720, Boise, ID 83720-0097, 2082874400



BROCKWAY
ENGINEERING
P.L.L.C.

Hydraulics

Hydrology

Water Resources

RECEIVED
JAN 03 2007
DEPARTMENT OF
WATER RESOURCES

December 27, 2006

Dave Tuthill
Idaho Department of Water Resources
322 E. Front Street
P.O. Box 83720
Boise, Idaho 83720-0098

Re: Notice of Error-Water Rights Valley Club Inc.
37-2623, 37-494, 37-657B, 37-495, 37-833K, 37-0577BU, 37-057BV

Dear Dave:

Enclosed are Notices of Error for the water rights which have been preliminarily recommended for The Valley Club Inc. The following table summarizes the items in the notices of error. Note that no preliminary recommendations are yet available for water rights 37-0577BV and 37-057BU.

Water Right No.	Disagreement	Reason
37-2623	Recommended Acreage 120.7 ac. recommended, should be 143.8 ac.	IDWR .shp file is incorrect See attached table and Brockway Engr .shp file
	Limitation condition on rate of diversion and volume is incorrect	37-0577T and 37-0577V should be 37-0577BV and 37-0577BU
37-494	Recommended Acreage 120.7 ac. recommended, should be 143.8 ac.	IDWR .shp file is incorrect See attached table and Brockway Engr .shp file
	Recreation use should indicate that 0.15 cfs is for pond consumptive use	
37-495	Recommended Acreage 120.7 ac. recommended, should be 143.8 ac.	IDWR .shp file is incorrect See attached table and Brockway Engr .shp file
	Limitation condition on rate of diversion and volume is incorrect	37-0577T and 37-0577V should be 37-0577BV and 37-0577BU

CHARLES E.
BROCKWAY,
PH.D., P.E.

CHARLES G.
BROCKWAY,
PH.D., P.E.

2016 NORTH
WASHINGTON
STREET • SUITE 4


TWIN FALLS,
IDAHO 83301

208•736•8543

FAX: 736•8506

	Diversion location is incorrect Location of Hiawatha Diversion should be SESWNW Sec 20 T3N R18E	
37-833K	Recommended Acreage 120.7 ac. recommended, should be 143.8 ac.	IDWR .shp file is incorrect See attached table and Brockway Engr .shp file
	Limitation condition on rate of diversion and volume is incorrect	37-0577T and 37-0577V should be 37-0577BV and 37-0577BU
	Recommendation should state that water right is part of the "Rockwell Bypass Right" and is always in priority as long as the Rockwell Bypass is flowing 17.36 cfs.	
	Diversion location is incorrect Location of Hiawatha Diversion should be SESWNW Sec 20 T3N R18E	Hiawatha Canal diversion is in the SESWNW Sec 20 T3N R18E
37-0577BU	No recommendation as of 12/28/06	
37-0577BV	No recommendation as of 12/28/06	
37-657B	Check PLS description for Hiawatha Canal diversion	West 9 golf Trans #71721

Sincerely,




Charles E. Brockway P.E.

Enclosures: Notices of Error
 .shp file for Valley Club Inc.
 Place of use spreadsheet

Cc: Valley Club Inc. Barry Beavers

Valley Club II					
Brockway Engineeing, PLLC					
2006 Irrigation Calculations-Golf Course Areas					
ALR - Dec. 27, 2006					
SEC	QQ	Acres	Irrig. 2006	Claimed	Recommended
20	NESE	3.28			
20	NESE	0.47			
20	NESE	8.69	12.44	15	11
20	NWNE	6.04			
20	NWNE	0.07	6.12	0	0
20	NWSE	1.14			
20	NWSE	0.78			
20	NWSE	9.14			
20	NWSE	2.59	13.65	15	11
20	SENE	6.65	6.65	7	5.9
20	SENE	1.57			
20	SENE	1.04	2.61	0	0
20	SESE	5.19			
20	SESE	0.21			
20	SESE	1.16	6.56	11	5.5
20	SWNE	0.66			
20	SWNE	3.93			
20	SWNE	11.77	16.36	11.5	11
21	SWSW	8.67			
21	SWSW	4.44	13.11	13.5	12
28	NENW	8.19	8.19	14.5	11
28	NENW	0.01			
28	NENW	8.61	8.63	7.5	8.2
28	NWNW	0.77			
28	NWNW	11.01			
28	NWNW	2.17			
28	NWNW	1.76			
28	NWNW	0.49	16.21	15	13
28	NWSW	8.67	8.67	11	7.7
28	SENE	10.07	10.07	10	10
28	SESW	2.14	2.14	2	1.4
28	SWNW	11.81			
28	SWNW	0.11			
28	SWNW	1.33	13.25	10.8	13
		144.64	144.64	143.80	120.70



BROCKWAY ENGINEERING, PLLC.
ALR - Dec. 29, 2006

Sum = 144.6 acres
Claim = 143.8 acres
Pre. Rec.= 120.7 acres

VALLEY CLUB II
2006 Irrigation calculation
NAIP 2006 Aerial photo

Legend

- Golf Irrigation 2006
- Section_Lines
- t03n18e