


Sheet 1

8-21-1980 NHAP 187-157

IDWR pictures 1-15

taken on (assumed) 6/2/2004
27-76 and 27-11317 "Draft"

map generated by HKM 3/07



Sheet 2

7-24-1987 NAPP 306-210


27-76, 27-11317



"Draft"
Map generated by HKM 3/07

notice where
the berm has
eroded out by
Meadow Creek


IDWR picture
#7



map marked by HKM in blue "draft"

12/14/2000

Water Right Claim Number 27-11317
Township, 5S42E



Legend

- | | | |
|--------------------|----------------------|--------------------|
| Irrigated Area | Section Line | Roads |
| Place of Diversion | Quarter Section Line | Streams and Canals |

500 0 500 1000 Feet



SPATIAL
DYNAMICS

NAPP 4937-144

8-27-1992

27-76, 27-11317

map generated by HKM "draft"

← Jarvis
Spring

← Willow
Spring

ditch
↓

← Chubb
Spring

← dry
hillside
included
in claim

→ In 1992 and
In 1987 there
was no way to
get water on the
west side of the old
channel of Meadow
Creek
15.2 ac.

→ ALL
Natural on
→ this side, no
diversions and
→ Nothing visited by
IDWR

map marked up by HKM "draft" 2/07

I 28-03
NOT TO
SCALE


3 9
10 11

water
477.49 feet per sec


221 ac 4.42 feet per sec

Stock water

ALL diversions from
Meadow Creek have
been abandoned for
20 years or more.



JUN 23 2004
JP



NAPP 306-210

7-24-1987

map generated by HKM "draft"

Chubb
Spring

dry hillside
included
in
claim

Chubb Spring was dry
on 7-24-1987

July 27, 1999

27-76, 27-11317

Photo taken by Saunders, HKM
Annotated by HKM 2/07

Jarvis
Spring

Willows
Spring

Road

ditch

Not Chubb
Spring

Chubb
Spring

Chubb
Spring

(S)