

MEMORANDUM

July 14, 2009

To: Monica Van Bussum

From: Bob Foster

Re: 75-4494A, 75-4496A

In response to Mr. Bishop's concern over ditch loss, I assume he is referring to the ditch from Hull Creek which is the conveyance system for 75-4496A. This ditch is of considerable length and traverses a gravely alluvial fan. The possibility for ditch loss in this conveyance system would be of some concern.

The issue of conveyance loss under right 75-4494A would be directly related to the efficiency of pumping system Mr. Bishop utilizes from the North Fork of the Salmon River. This reach of the North Fork of the Salmon River is not flow impaired during the irrigation season.