

RECEIVED

DEC 16 2009

DEPARTMENT OF
WATER RESOURCES

Memorandum

Date: 12/14/09

73-12049

To: Don Shaff

From: Bob Foster

Re: Dreyer/ NW Fidelity

I met with Bob Dreyer on December 10, 2009 on property located in the SESE, S 13, R 23E, T 13N. The purpose of this visit was to verify irrigation on this property.

At the time of my visit no water was being diverted to the property. There is a conveyance system consisting of a main ditch running west along the north edge of the property. This ditch has several small feeder ditches running to the south to convey water to the land in question.

The vegetation on the land consists of sagebrush approximately 12 to 24 inches in height interspersed with native grasses. There is no evidence of cultivation on this land but the amount of native grasses present would probably not be as abundant unless water has been applied to the land. Mr. Dreyer stated water is applied early in the season (when available) and the ground is used as summer pasture. I would estimate there are approximately 25-30 acres utilized for this purpose.

T 13
R 23E
S 13

13

POU

main
Ditch




Looking east at main ditch. (Dreyer property) 12/10/09



Main ditch looking west (Dreyer property) 12/10/09



main ditch on north edge of property (Dreyer) 12/10/09



Looking west across POU (Dreyer) 12/10/09



small feeder ditch running south from main ditch (Dreyer) 12/10/09



POU looking SW small feeder ditch in foreground (Dreyer) 12/10/09