


SANDERS PINZOTTI PIN 49N02W-34-5000

RECEIVED

JUN - 2 2010

IDWR/North



not
developed
yet

This
spring is
to be tied
into the
house line
All of the
springs
flow into
ground.

the
well is
not used
because
the line
to the house
is broken,
so it is
not in use
at this
point.

94-7562