

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORTRECEIVED Use Typewriter
or
Ball Point Pen
MAR 18 2013

JUN 23



IDWR/NORTHERN 1408


1. DRILLING PERMIT NO. 95-79-N-33-400
Other IDWR No. _____

2. OWNER:

Name John O'Brien
Address 6303 Mullaw Trail Rd.
City Coeur d'Alene State ID Zip 83814

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

T. 50 North ☒ or South ☐
E. 3 East ☐ or West ☒
Sec. 21 1/4 SE 1/4 SE 1/4
Gov't Lot _____ County BozemanAddress of Well Site Same as Owner

(Give at least Direction + Distance to Road or Landmark)

Lot No. _____ Block No. _____ Subd. Name _____

4. PROPOSED USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK

☐ New Well ☒ Modify or Repair ☐ Replacement ☐ Abandonment

6. DRILL METHOD

☐ Mud Rotary ☒ Air Rotary ☐ Cable ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT		METHOD
Material	From	To	Sacks or Pounds		

Was drive shoe seal tested? ☐ YES ☐ NO How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Casing	Liner	Steel	Plastic	Welded	Threaded
4	-10	200	1/2		NC	☐	☒	☒	☐
						☐	☐	☐	☐
						☐	☐	☐	☐
						☐	☐	☐	☐

Final location of shoes

Top Packer or Headpipe 147 Bottom Tailpipe _____

9. PERFORATIONS/SCREENS

☒ Perforations Method _____
☐ Screens Type _____ Material _____

From	To	Slot Size	Number	Diameter	Tele/Pipe Size	Casing	Liner
160	200	1/2 x 4	80		4	☐	☒
						☐	☐
						☐	☐
						☐	☐

SESE 21 50N 3W

10. WELL TESTS:

☐ Pump ☐ Baller ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Depth	Time
40			4 hrs

Temperature of water 60 Was a water analysis done? Yes ☐ No ☒

By whom? _____

Water Quality (odor, etc.) good no odorBottom Hole Temperature 60

11. STATIC WATER LEVEL:

150 ft. below surface Depth artesian flow found _____

Artesian pressure _____ lb. Describe access port _____

Describe Controlling Devices: well cap

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	GPM	SWL
			Cleaned & Relined said well. Packers at 147 & 150 Note*		
			Well was originally sub standardly constructed By Coeur d'Alene Drilling #214 In 1977		
			Fix well with best AQUA Drilling could without without Major Reconstruction which would not be cost effective Verses starting over with a New Well. This well should have been cased farther with 6" steel casing when originally drilled by Coeur d'Alene Drilling #214		
			RECEIVED OCT 9 1996 AUG 22 1996 Department of Water Resources		
			Date: Started <u>7-21-94</u> Completed <u>7-25-94</u>		

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name AQUA DRILLING & EXPLORATION INC. Firm No. 163Firm Official Scott M. Beam Date _____and
Supervisor or Operator Don Montoya Date 7-26-94

(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES