

MEMORANDUM

TO: Water Right 74-16111

FROM: Daniel A. Nelson

DATE: August 15, 2022

SUBJECT: In-ability to Perform an In-House Field Exam

I reviewed this file to perform an in-house examination and determined that the locations of the water troughs may not be in a location shown on the permit maps. I strongly recommend that this permit be field examined to GPS the water trough locations.

I suspect that the water trough in the SWNE of Section 26 is in the NWNE of Section 26. I also suspect that the water trough in the NWNW of Section 35 is in the NENE of Section 34. There also appears to be an extra water trough in the NESW of Section 26.

I feel it would be in the best interest of the client to properly locate the water troughs to make sure they are properly covered.