

MEMORANDUM

TO: Water Right Permit File 95-10945

FROM: Daniel A. Nelson

DATE: December 2, 2020

SUBJECT: In-house Field Exam

We attempted to perform an in-house field exam on this permit. There does look as though there is an area that was cleared for a yard, and the trees appear to have been thinned for the entire parcel. There are two parcels owned by permit holder, but this permit is only for the northern most parcel described as Lot 1, Block 1, Park Ridge Subdivision. The other parcel (Lot 2, Block 1, Park Ridge Subdivision) already has an existing water right (95-9415) on it.

I don't want to limit the irrigation use to just the yard area if they are also irrigating the remainder of the parcel where the trees have been thinned out. I feel it would be best if an agent visited the property to determine exactly what is happening, and it wouldn't hurt to see if the water systems for the two parcels are tied together or not. This one just has a number of questions that I think would warrant an agent visiting the property.