

Permit No. 11-7451
Name Stoker

**STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES
In-Office Beneficial Use Examination**

1. ✓ Copy of Permit
2. ✓ Copy of proof of beneficial use
3. N/A Copies of amendments/orders
4. Y Qualifies under Rule 35.01.r (IDAPA 37.03.02)
5. ✓ Point of Diversion

Township 14S, Range 46E, Section 27, QQ SENW

Method used to determine POD: Aerial photo

6. _____ Place of Use

Township 14S, Range 46E, Section 27, QQ NWNE

Method used to determine POU: Aerial photo

7. No POD and POU match Permit Approval → Amendment needed for POD

8. ✓ Aerial photo of place of use

9. N/A Well driller's report

10. No Within a water district? (WD# —)




- ## 11. _____ Volume Calculation

12. ✓ Other information: Current owner is MJM Properties LLC (Mike McMillan)
3955 W. Old Hwy Rd.
Morgan, UT 84050

Examiner Name James Cefalo Date Sept 26, 2016

Reviewer _____ Date _____

Water Right License 11-7451



M E M O R A N D U M

Date: September 26, 2016
To: Water Right File 11-7451
From: James Cefalo
Re: Field Report Narrative

Field exam completed in office after conversation with current property owner, Mike McMillan. Spring was developed for use at one home. Shortly after permit was issued and proof of beneficial use filed, property was sold by permit holder, Stoker, to McMillan. He has also used the spring water for stockwater. Source identified as "spring" in original application, "unnamed stream" in the amended application, and "unnamed stream" in the permit. Correct source designation is spring tributary to sinks.

MEMORANDUM

Date: September 26, 2016
To: Water Right File 11-7451
From: James Cefalo
Re: Spring Location

Permit identifies spring location in the SWNE of Section 27, T14S, R46E. Based on aerial photos and conversation with current property owner, Mike McMillan, spring is actually located in the SENW of Section 27. Spring is located right on property boundary according to Bear Lake County taxlot information. However, taxlot boundaries appear to be shifted slightly. McMillan stated that the property was surveyed and the spring is located approximately 60 feet inside of his property. Existing fence lines would have the spring located on the McMillan property. License will be issued with condition about not granting an easement.