

**SPF**

Water Engineering, LLC
water resource consultants

RECEIVED

APR 25 2006

DEPARTMENT OF
WATER RESOURCES

April 24, 2006

Tim Luke
Idaho Department of Water Resources
Statehouse Mail
P.O. Box 83720
Boise, ID 83720-0098

Subject: Water Level Monitoring for Licenses 63-11995, 63-11996, and 63-12450

Dear Tim:

Enclosed for Department records, please find a summary of water level measurements required as a condition of the above referenced licenses

Please contact me with any questions.

Sincerely,

Terry M. Scanlan, P.E., P.G.

Enclosure

Cc: Joy Lynn

	M. Lynn	C. Lynn	Lynn Old
Date	Domestic Well	Domestic Well	Irrigation Well
9/9/1993		394.4	382.5
10/21/1994	394.76	394.02	383.40
1/22/1995	395.32	394.25	382.23
3/24/1995	395.48	394.29	382.78
5/21/1995	397.28*	394.66*	382.53
8/27/1995	394.64	394.09	388.45*
10/22/1995	394.61	394.30	383.45*
3/16/1996	395.44	394.49	382.48
10/29/1996	394.66	394.26	382.44
3/26/1997			381.51
10/18/1997	395.15	394.55	383.15
4/16/1998	396.48	394.45	
10/21/1998	395.44	394.74	382.60
3/20/1999	395.76	394.59	382.30
10/21/1999	395.35	395.20*	383.07
3/31/2000	395.90	395.06	382.41
10/26/2000	394.63	394.40	382.24
3/24/2001	395.33	394.92*	382.10
10/30/2001	394.78	**	381.65
3/21/2002	395.73		382.11
10/31/2002	397.44*		383.66
3/10/2003	396.44		382.67
3/24/2004	396.48		382.99
3/31/2005	397.65		384.05
10/27/2005	395.77		395.33***
4/17/2006	396.68		395.24***

* recovering slowly from recent pumping

**sounding tube removed during well repair

***pumping?