

4/7/2015

Page 1 of 4

IDAHO DEPARTMENT OF WATER RESOURCES
Proof Report

4/7/2015

full amount, however, so I can only recommend 0.07 cfs for irrigation under the 3 parts of 37-7603 (20622, 20623, & 20452). GIS shows a small amount of land in the SW/SE Sec. 4, with the rest in the NW/SE Sec. 4. The GCDB for 2N 18E was originally rectified incorrectly, but this was corrected last summer; licensing recommendations are based on the corrected data.

2. kwalker 5/14/2002 License Recommendations
The permit holders failed to submit the required licensing amendment for this permit. The license can only be issued for the portion of the right that did not need amended, therefore, this right is being recommended for 0.1 acres only.
5/16/02 We received licensing amendment in mail. Recreated license as examiner recommended.

3. amerritt 9/2/2005 removed remark
Removed the following remark since transfer 72125 move right 37-20452 to another well.
Remark removed: Right No. 37-20452 is also diverted through the point of diversion described above.

4. tfawcett 3/9/2015 split right
This right was split into 37-20622 and 37-22925 pursuant to an ownership change.

5. tfawcett 4/6/2015 POU
Updated Shape

6. tfawcett 4/6/2015 POU
Updated PLS

Combined Use Limits

N/A

SubCase:

N/A

Water Supply Bank:

N/A