



State of Idaho

DEPARTMENT OF WATER RESOURCES

Southern Region, 1341 Fillmore Street, Suite 200 • Twin Falls, Idaho 83301-3380

Phone: (208) 736-3033 • Fax: (208) 736-3037 • Web Site: www.idwr.idaho.gov

February 3, 2009

Nutrient Management Solutions
1255 Filer Ave East
Twin Falls, ID 83301

C. L. "BUTCH" OTTER
Governor

DAVID R. TUTHILL, JR.
Director

RE: Your Letter Dated RE John Cardozo Property In SW/NW Sec. 26 T. 10S R. 14E

Dear Bob;

Our records show two dairy wells and one domestic well located in the NW/SW Sec. 26 under Water Rights 47-7663F and 47-14200, respectively. There are no water rights for two homes listed in the tract being split, however. Your letter states that there are two existing homes on the land being split off from the rest of the Cardozo property, but does not provide any other specific information that I can respond to (exactly what well serves the homes?; when were they built?; is the well used for outside watering?). Printouts of the Cardozo water rights are enclosed for your information. Feel free to contact me again when you have more information.

Regards,

James E. Stanton
Sr. Water Resource Agent

47-17503