

WATER DISTRICT 34

P.O. Box 53
Mackay, Idaho 83251

March 27, 2013

To whom it may concern,

On March 25, 2013 I was asked
by Gordon Fulton to remeasure the
Rock creek weir. I measured the weir
at 3:30 PM and found them to be
.2095 CFS.

Gordon

1.026 CFS at 4' weir
= 51.3 inches
x .2095 at 6" weir
= 10.48 inches

Sincerely

Roger Toth

Watermaster District 34