

Memorandum

Date: January 18, 2013

To: file 65-22647

From: Craig L. Saxton

The GCDB, Taxlot lines, and the air photos don't quite line up. It makes it look like part of the POU is in the SESW of Section 26 when according to the subdivision plat, all of the POU is within the SWSW of section 26. Therefore the license is being issued with the POU only in the SWSW of S.26. The POU that is in ArcMap was drawn over the subdivision as displayed on the aerial photo, and then once the acreage was determined, the shape was shifted to the west so it falls completely in the SWSW of S26. If you look at the shape in ArcMap, it doesn't fit the aerial photo so it looks off. But this was intentional.

